

## Potential Safety Hazard for Hobart Mixer: Inspect Bowl Guard Hardware Immediately

---


**Topic:** Model HL200 Hobart Mixers may have loose hardware (screws/nuts) on bowl guard.

**Solution:** Perform safety inspection, checking screws/nuts on bowl guard. Contact Hobart for replacement bowl guard if hardware is loose.



### Mixer Safety Inspection

- To prevent screws/nuts from falling into product that could be served to customer, inspect Hobart HL200 mixer (countertop model AND free-standing, floor model) immediately for loose parts on bowl guard.



### Bowl Guard:

Check 3 bowl guard screws (top side) and 3 nuts (bottom side).

- If any loose bowl guard items are detected, contact **Mary Fritz** at Hobart Corporation Customer Service at [937-332-2497](tel:937-332-2497) or [mary.fritz@hobartcorp.com](mailto:mary.fritz@hobartcorp.com).
  - ❑ Operator must provide mixer serial #, shipping address and contact phone number.
  - ❑ Hobart will ship Restaurant a new replacement bowl guard overnight **at no charge**.